

One Jumper (cord) Reference Method

Setting Reference: Step 1


IMPORTANT: Inspect and, if necessary, clean all test reference cords (TRCs) prior to making any connections

- Connect TRC-1 from Transmit to Receive
- Connect TRC-2 to the other Tx and Rx ports



Setting Reference: Step 2

Add TRC 3 and TRC 4 as shown below



All Reference Test Cords for testing of LC connections shall be replaced when the test reference value is equal to or greater than **0.25 dB**.

Remember that this will show up in the recorded reference value results.

*Per MS 27.08.20
Revision 10 document*

You are now ready to test!



- Save reference verification results as a test record
- Select the desired cable id from the list and begin testing

REMEMBER:

After every **500** LC tests, you must re-reference and save the verification results!